



Your Burner Specialists

Call Today! 773.737.9200

Visit our website  
[www.ACSIGroup.com](http://www.ACSIGroup.com)

## Cold Weather: Boilers Working on Over Drive

The winter weather has placed a great amount of stress on boilers and burners. This results in higher energy costs and the risk of repairs.

Our professional technicians have witnessed many facilities postponing their repairs until absolutely necessary. Unfortunately it comes at a cost.

At the first sign of trouble, get ACSI's service technician to evaluate the issue right away. By delaying the repair, the problem continues to grow costing you more as each day passes.

If you're ready to stay on top of the problems even before they start, join ACSI's maintenance program.



For emergency service, contact us day or night at 773.737.9200

## How to Check for Refractory Problems

Boilers can last for many years without replacement. To get the most from your boiler, be sure to perform our top 3 routine checks. Inspect for...

- Hot spots on the outer shell
- Paint burning on the outer skin
- Steel glowing red from overheating

If any of these signs are apparent, you will need to slowly cool down the boiler prior to entering, to visually inspect the refractory on the inside.

- Search for large cracks or broken/missing pieces
- Search for small hairline cracks.
- Search for bricks that have fallen out or show excessive wear.

A yearly routine "point and paint" maintenance procedure can save you on costly repairs and purchases. **Call Bill directly at 708 478-7744 for a free inspection.**



## Did You Know...

ACSI installs and maintains chillers in high rise buildings?



ACSI installs and maintains crematories, ovens, kilns and furnaces?



Call Today! 773.737.9200