



Your Burner Specialists

Call Today! 773.737.9200

**Visit the new website at:
www.ACSIGroup.com**

Before the Real Cold Sets in, Inspect the Refractory

Getting the refractory inspected sooner than later can save you unnecessary downtime, substantial costs, and undue stress. It is recommended that your boiler, furnace, or oven be inspected annually. With proper maintenance and care, you will be able to extend its useful life.

If you experience one of our stated 'Top 3 Ways to Identify a Refractory Problem', then you are ready for a refractory inspection. In order to do this, the boiler, furnace, or oven must be turned off and cooled down enough to safely enter. Depending on the equipment type, this cool down can take as little as 8 hours, or as long as two to three days.



Top 3 Ways to Identify a Refractory Problem:

1. If you feel any hot spots on the outer shell.
2. If you literally 'see' paint burning away from the outer skin.
3. If the steel is glowing.

Once inside, a visual inspection will reveal any issues. If large cracks or broken/missing pieces are found, it will

require repair or replacing. Small hairline cracks are of the norm. A yearly routine "point and paint" maintenance procedure on these cracks can extend its life and be completed with a high temperature bonding or air-dry mortar mix.

American Refractories will handle your repairs....from the smallest to the largest!

Call our refractory Foreman, Bill Scott, directly at 708- 478-7744.

Thinking of installing a new high efficient burner?

We can provide you with a "Cost Savings Estimate" – So you can see what your projected Return On Investment (ROI) would be. (Most come in under 3 years!)After that.....the savings continue to go back into your pocket.....year after year after year!



Go to www.acsigroup.com/Installation.aspx

New, Obsolete or Hard to Find Burner Parts are ACSI's Specialty

ACSI works with many facility managers across the country supplying old, obsolete, hard to find and even new parts.

We recommend replacement components that can do the same job or in some cases, fabricate obsolete parts.

**For help with hard to find parts call ACSI at
773.737.9200.**

REBATES.....from the gas companies!

Have ACSI tune up your burner(s) and take advantage of the rebates offered through Peoples Gas Co. and Nicor. Hundreds of dollars are given back through this program - to help offset the burner tune-up costs. You not only get the rebate money....you also save money by using less energy with a "tuned – up" fuel burner!

Call Today! 773.737.9200